

3013

B.Tech. 2nd Semester G-Scheme (Common for all Branches) Examination, May-2019

WORKSHOP TECHNOLOGY

Paper-ESC-ME-102-G

Time allowed : 3 hours]

[Maximum marks : 75

Note : Question No. 1 is compulsory. Attempt one question from each unit.

- 1. Explain the following : 6×2.5=15
  - (a) Define Fettling in the castings.
  - (b) What is extrusion ?
  - (c) What is the function of flux in welding ?
  - (d) List the operation performed on lathe machine.
  - (e) Causes of Accident.
  - (f) What do you mean by piercing ?

Unit-I

- 2. Explain Additive in Manufacturing process, also describe the methods of safety. 15
- 3. Enlist various types of accident. How can minimise them give an suitable examples. 15

Unit-II

- 4. Describe various sheet metal operations with the help of neat sketches. 15

3013-P-3-Q-9(19)

[P. T. O.

(2)

3013

- 5. Explain the Rolling, forging, Drawing, Wire drawing and spinning. Also tell the types of timber and its's defects. 15

Unit-III

- 6. Describe the various types of pattern and allowances. 15
- 7. Explain the cupola furnace with the help of neat sketches, also tell casting defects and its remedies. 15

Unit-IV

- 8. (a) Differentiate between Arc welding and gas welding. 7
  - (b) How do you compare A.C. and D.C. arc welding? 8
- 9. (a) Describe MIG welding with the help of neat sketch. 10
  - (b) Differentiate between soldering and brazing. 5

https://www.haryanapapers.com

Whatsapp @ 9300930012

Send your old paper & get 10/-

अपने पुराने पेपर्स भेजे और 10 रुपये पायें,

Paytm or Google Pay से

3013